

DOMINANT BUILDING MATERIALS

The dominant building material in Kensington is wood, executed either as clapboard and weatherboard. Thirty-five percent of the historic structures in Kensington are clad in wood, and retain much of their original wood trim. Additionally, 11% of the structures are clad with wood shingles, typical of the Shingle and Queen Anne styles. A large number of historic resources have been clad with new building materials, and have lost much of their exuberant detailing and ornamentation. 22% percent have been clad in aluminum or asphalt siding. Sixteen brick structures are located in Kensington, or 11% percent of the historic resources are brick. Eight stucco buildings are located in the district, comprising 5% of the residential building fabric.



Figure 14: Dominant Building Materials in Kensington: Clapboard and Brick.

KENSINGTON HISTORIC DISTRICT

FREQUENCY REPORT


FOR THE FIELD Relationship of Materials [MAIN->RELATEMAT]

Uses Code Text

```
=====
      1 40            Stone
      4 WS            Wood Shingle
     13 ST            Stucco
     13 VI            Vinyl
     15 AB            Asbestos
     19 AS            Asphalt
     53 AL            Aluminum
     86 BR            Brick
    158 WO            Wood
=====
```

9 DIFFERENT CODES ARE USED 362 TIMES
FOR 187 MARKED RECORDS

Stone	1
Wood Shingle	4
Stucco	13
Vinyl	13
Asbestos	15
Asphalt	19
Aluminum	53
Brick	86
Wood	158



KENSINGTON HISTORIC DISTRICT

FREQUENCY REPORT FOR THE FIELD Relationship of Textures [MAIN->RELATETEX]

Uses Text

1	Stone
6	Stucco
13	Shingles
28	Siding
43	Brick
90	clapboard

6 DIFFERENT CODES ARE USED 181 TIMES
FOR 187 MARKED RECORDS

Stone	1
Stucco	6
Shingles	13
Siding	28
Brick	43
Clapboard	90

