

INTEGRITY OF FORM, BUILDING CONDITION AND THREATS

The majority of buildings in Kensington maintain their original configurations and architectural treatments. These buildings have been carefully maintained and, in many cases, restored with painstaking care.

The majority of historic buildings are in good condition. Only one building is cited in a deteriorated condition. No immediate threats were identified.



Figure 16: Photograph of 3810 Warner Street

KENSINGTON HISTORIC DISTRICT

FREQUENCY REPORT

FOR THE FIELD Condition of a Resource [MAIN->CONDITION]

# Uses	Code	Text
1	D	Deteriorated
6	E	Excellent
13	F	Fair
167	G	Good

4 DIFFERENT CODES ARE USED 187 TIMES
FOR 187 MARKED RECORDS



KENSINGTON HISTORIC DISTRICT

FREQUENCY REPORT

FOR THE FIELD Threats to Resources [MAIN->THREAT]

# Uses	Code	Text
2	4	Deterioration
2	5	Other
4	I	Inappropriate alterations
179	1	None

4 DIFFERENT CODES ARE USED 187 TIMES
FOR 187 MARKED RECORDS

